Erasure Report

2022-01-11 / 12:03

Organization	Operator
KVS Computers	Kem

GF2301741

ATA / FUJITSU MHY2160B

Erasure success

Vendor / Model	ATA / FUJITSU MHY2160B	Erasure level achieved	High security
Serial number	K43AT893482M	Erasure standard	NIST.SP.800/ATA Clear
Type	HDD	Erasure passes	1
Command protocol	ATA	Erased sectors	100% (312581808)
Transport	SATA	Verified sectors	5% (15629090)
Size	160.0GB	Erasure started	2022-01-11 09:39
Size (bytes)	160041885696	Erasure time	1h 43m 40s
Sectors	312581808	Errors	0
Sector size (bytes)	512	Secure Erase	Not Attempted, estimated to 160 min
Remapped sectors	0	Enhanced Secure Erase	Not Attempted, Time estimation not found
HPA	Not found	Security	Not frozen
DCO	Not found		
Raw Read Error Rate	0		
Throughput Performance	0		
Spin Up Time	0		
Start Stop Count	3189		
Power On Hours	15298		
Temperature Celsius	27 (Min/Max -2/49)		

Report Details

Report signature	Verified	LOT number	GF2301741
Report tag	GF2301741	Contact person	
Report date	2022-01-11 12:03	Location	
Report ID	01180eb3-294a-41e0-8790-c016e32edd96	Department	
Session ID	a5114a84-b6b8-4af5-8fc9-6b8d57f0b02e	Branch	
Erasure software	YouWipe 4.1.256.2306052336-a8432d96		

Hardware Details

Model	MacBook4,1
Serial number	System Serial#
Processor	GenuineIntel,Intel(R) Core(TM)2 Duo CPU T8300 @ 2.40GHz,x86_64 @ 2.4GHz, physical CPUs: 1, logical CPUs: 2, Speed: 2400MHz
Memory	2GiB
VGA compatible controller	Intel Corporation Mobile GM965/GL960 Integrated Graphics Controller (primary)
Network controller	Broadcom Inc. and subsidiaries BCM4321 802.11a/b/g/n
Ethernet controller	Marvell Technology Group Ltd. 88E8058 PCI-E Gigabit Ethernet Controller
Audio device	Intel Corporation 82801H (ICH8 Family) HD Audio Controller
SATA controller	Intel Corporation 82801HM/HEM (ICH8M/ICH8M-E) SATA Controller [AHCI mode]
IDE interface	Intel Corporation 82801HM/HEM (ICH8M/ICH8M-E) IDE Controller

Operator:

Supervisor:

