Site	KVS - Production 1
Date	10/31/23 15:18:58
Global Result	OK

Model	Apple Inc. - iMac19,2
Chassis type	LapTop
Serial / UUID	C02Z84YPJWDW / 921BA196-E7D8-5133-B592-31A450AAEBDA
Processor	INTEL CORE I3-8100 @ 3.1GHz
Memory	8GB - BANK 0 - SODIMM: 4GB DDR4 2400MHz (HMA851S6CJR6N-VK) BANK 2 - SODIMM: 4GB DDR4 2400MHz (HMA851S6CJR6N-VK)
Disk	HDD HITACHI APPLE HDD HTS541010A9E632 1.00 TB - S/N:JD8008D8JT981S - Health:Good
Graphics Card	Baffin [Radeon RX 460/560D / Pro 450/455/460/555/555X/560/560X]
Sound Card	High Definition Audio Device
Network Adapter	Wired - Broadcom NetXtreme Gigabit Ethernet 1000Mbps (80:4A:14:62:03:17)
Network Adapter	Wireless - Broadcom 802.11ac Network Adapter (A4:83:E7:9E:7F:0E)
Motherboard	Apple Inc. Mac-63001698E7A34814 - Version:iMac19,2 - S/N:C02933701N3KGQ32N
BIOS	Apple Inc. - Version:1731.100.125.0.0 - Date:01/20/2022

Report Details

Hardware Diagnostics

- ✓ **Internal Speaker Skipped - Feature previously tested**
- ✓ **Keyboard Result set by the operator**
- ✓ **HDD Short SMART Test**
- ✓ **Touchpad Skipped - Feature not present**
- ✓ **Webcam**
- ✓ **Battery Wear Level Skipped - Feature not present**
- ✓ **Dead Pixel Test**
- ✓ **RAM**
- ✓ **General purpose instructions**
- ✓ **Maximum heat**
- ✓ **2D Local video memory**

Data Erasure

✓ **Disk(s) wiped:** HITACHI APPLE HDD HTS541010A9E632 1.00 TB - S/N:JD8008D8JT981S - Health Status:Good
Wipe algorithm: Clear with 0 (NIST 800-88) (1) - 03:39:01

I hereby state that the data erasure process has been carried out in accordance with the given instructions.

Solution developed by:

Part of hardware diagnostics provided by:

Secure wipe certified by: