Erasure Report

2022-11-11 / 17:18

Organization	Operator
KVS Computers	cherif

GF2200431

JMicron / Tech

Erasure success

Vendor / Model	JMicron / Tech	Erasure level achieved	Baseline security
Serial number	DD56419883893	Erasure standard	HMG Infosec Low
Type	SSD	Erasure passes	1
Command protocol	Virtual Disk	Erased sectors	100% (500118192)
Transport	Failed to detect	Verified sectors	3% (15003540)
Size	256.1GB	Erasure started	2022-11-11 09:13
Size (bytes)	256060514304	Erasure time	2h 2m 20s
Sectors	500118192	Errors	0
Sector size (bytes)	512		
Remapped sectors	0		

(*) All user accessible areas have been erased successfully. Disk may contain user inaccessible areas which are primarily used by hardware vendors to store system or defective information. In case these areas are also required to be erased, use extended erasure standards or contact our support for more help.

Report Details

Report signature	Verified	LOT number	GF
Report tag	GF2200431	Contact person	
Report date	2022-11-11 17:18	Location	
Report ID	0ae66a3e-3fee-48d9-b284-b69b9883af58	Department	
Session ID	24fdd98f-4525-4d8c-bcf3-153f6bd5bb4a	Branch	
Erasure software	YouWipe 4.1.241.2209301840-37960560		

Hardware Details

Model	Precision T3610
Serial number	3QLRY12
Processor	GenuineIntel,Intel(R) Xeon(R) CPU E5-1620 v2 @ 3.70GHz,x86_64 @ 3.9GHz, physical CPUs: 1, logical CPUs: 8, Speed: 3900MHz
Memory	16GiB
VGA compatible controller	NVIDIA Corporation GK208B [GeForce GT 730]
Ethernet controller	Intel Corporation 82579LM Gigabit Network Connection (Lewisville)
Audio device	Intel Corporation C600/X79 series chipset High Definition Audio Controller
Audio device	NVIDIA Corporation GK208 HDMI/DP Audio Controller
SATA controller	Intel Corporation C600/X79 series chipset 6-Port SATA AHCI Controller
IDE interface	Intel Corporation C600/X79 series chipset IDE-r Controller
RAID bus controller	Broadcom / LSI SAS2008 PCI-Express Fusion-MPT SAS-2 [Falcon]
RAID bus controller	Broadcom / LSI SAS2008 PCI-Express Fusion-MPT SAS-2 [Falcon]

Operator:

Supervisor: