Erasure Report

2023-08-15 / 22:11

Organization	Operator
KVS Computers	Samuel

GF2304132

ATA / Hitachi HTS54505

Erasure success

Vendor / Model	ATA / Hitachi HTS54505	Erasure level achieved	High security
Serial number	090720PBC400Q7HBSZBL	Erasure standard	NIST.SP.800/ATA Clear
Type	HDD	Erasure passes	1
Command protocol	ATA	Erased sectors	100% (976773168)
Transport	SATA	Verified sectors	6% (48838660)
Size	500.1GB	Erasure started	2022-01-11 09:40
Size (bytes)	500107862016	Erasure time	3h 54m 37s
Sectors	976773168	Errors	0
Sector size (bytes)	512	Secure Erase	Not Attempted, estimated to 156 min
Remapped sectors	0	Enhanced Secure Erase	Not Attempted, estimated to 158 min
HPA	Not found	Security	Not frozen
DCO	Not found		
Raw Read Error Rate	0		
Throughput Performance	0		
Spin Up Time	1		
Start Stop Count	10578		
Power On Hours	11723		
Temperature Celsius	27 (Min/Max 8/42)		

Report Details

Report signature	Verified	LOT number	GF2304132
Report tag	GF2304132	Contact person	
Report date	2023-08-15 22:11	Location	
Report ID	23446c05-c7cf-4ec0-8816-6dfa635f6ff3	Department	
Session ID	187d9090-36c8-430c-a1fa-9df0ca85355b	Branch	
Erasure software	YouWipe 4.1.250.2302202046-2e399f7a		

Hardware Details

Model	MacBookPro5,3
Serial number	73945012B22
Processor	GenuineIntel,Intel(R) Core(TM)2 Duo CPU T9600 @ 2.80GHz,x86_64 @ 2.8GHz, physical CPUs: 1, logical CPUs: 2, Speed: 2793MHz
Battery Info	Vendor: SMP,Model: bq20z451, Serial: , Type: lithium-ion, Capacity: Some(82)%, Voltage: Some(11.0) V
Battery Test	Battery health OK
Memory	4GiB
VGA compatible controller	NVIDIA Corporation G96CM [GeForce 9600M GT]
VGA compatible controller	NVIDIA Corporation C79 [GeForce 9400M]
Network controller	Broadcom Inc. and subsidiaries BCM4322 802.11a/b/g/n Wireless LAN Controller
Ethernet controller	NVIDIA Corporation MCP79 Ethernet
Audio device	NVIDIA Corporation MCP79 High Definition Audio
SATA controller	NVIDIA Corporation MCP79 AHCI Controller

Operator:

Supervisor:

