Erasure Report

2023-05-31 / 16:37

Organization	Operator
KVS Computers	Samuel

GF2301586

ATA / SanDisk SD8TB8U2

Erasure success

Vendor / Model	ATA / SanDisk SD8TB8U2	Erasure level achieved	Baseline security
Serial number	164532800905	Erasure standard	NIST.SP.800/ATA Clear
Type	SSD	Erasure passes	1
Command protocol	ATA	Erased sectors	100% (500118192)
Transport	SATA	Verified sectors	6% (25005910)
Size	256.1GB	Erasure started	2023-05-31 11:03
Size (bytes)	256060514304	Erasure time	33m 14s
Sectors	500118192	Errors	0
Sector size (bytes)	512	Secure Erase	Not Attempted, estimated to 2 min
Remapped sectors	0	Enhanced Secure Erase	Not Attempted, estimated to 2 min
HPA	Not found	Security	Not frozen
DCO	Not supported		

(*) All user accessible areas have been erased successfully. Disk may contain user inaccessible areas which are primarily used by hardware vendors to store system or defective information. In case these areas are also required to be erased, use extended erasure standards or contact our support for more help.

Report Details

Report signature	Verified	LOT number	GF2301586
Report tag	GF2301586	Contact person	
Report date	2023-05-31 16:37	Location	
Report ID	c4103b6c-63a9-4a01-b3a6-0e36ac98a7ec	Department	
Session ID	6a2742be-267e-4e63-99f6-9d094b95a5f1	Branch	
Erasure software	YouWipe 4.1.250.2302202013-042a2b28		

Hardware Details

Model	20BV000AUS
Serial number	PC09LMYK
Processor	GenuineIntel,Intel(R) Core(TM) i5-5300U CPU @ 2.30GHz,x86_64 @ 2.9GHz, physical CPUs: 1, logical CPUs: 4, Speed: 2900MHz
Battery Info	Vendor: SANYO,Model: 45N1773, Serial: 21317, Type: lithium-ion, Capacity: Some(75)%, Voltage: Some(9.0) V
Battery Test	Battery health OK
Memory	4GiB
VGA compatible controller	Intel Corporation HD Graphics 5500
Network controller	Intel Corporation Wireless 7265
Ethernet controller	Intel Corporation Ethernet Connection (3) I218-LM
Audio device	Intel Corporation Broadwell-U Audio Controller
Audio device	Intel Corporation Wildcat Point-LP High Definition Audio Controller
SATA controller	Intel Corporation Wildcat Point-LP SATA Controller [AHCI Mode]

Operator:

Supervisor: